



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
November 9, 2009

Reviewed: MBP

Mine Name: Soma Quarry	Permit Number: S0230065
Operator Name: Nephi Sandstone Corp.	Inspection Date: November 5, 2009
Inspector(s): Wayne H. Western	Time: 5:15 PM
Other Participants: None	Mine Status: inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

The purpose of the inspection was to determine if the overhang had been removed.

Directions to Site:

The site is located east of Leamington, Utah on the south bank of the Sevier River. Approximately 2.3 miles northeast of the cement plant, 39° 35' 08.66" N 112°09' 54.96"

Inspection Summary:

The Operator had removed most of the overhangs. There are still some minor overhangs. The slope needs to be reduce to no more than 45 degrees.

Conclusions and Recommendations:

As part of the general mine plan, the Permittee should lay the highwall back to a 45-dregree slope or less. Continue to monitor this site when in the area.

Inspector's Signature

Wayne H. Western 01/12/2010

Inspection Date: November 5, 2009
Page 2 of 3

S/023/0065


WHW

cc: (OPERATOR)

Jerry_Mansfield@BLM.gov

O:\M023-Juab\S0230065-Soma\draft\insp07142009.doc

S/023/0065



After



Before